



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director GARY R. HERBERT Lieutenant Governor

JON M. HUNTSMAN, JR. Governor

Representatives Present During the Inspection: Company Kit Pappas Manager of Environmental/Engineering Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070020
Inspection Type:	PARTIAL
Inspection Date:	Thursday, December 11, 2008
Start Date/Time:	12/11/2008 9:30:00 AM
End Date/Time:	12/11/2008 12:30:00 PM
Last Inspection:	Thursday, November 06, 2008

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 35 Deg. F. InspectionID Report Number: 1860

Types of Operations

Reprocessing

Accepted by: Jhelfric

1/6/2009

Permitee: HIDDEN SPLENDOR RESOURCES INC Operator: HIDDEN SPLENDOR RESOURCES INC

Site: HORIZON MINE

Address: 3266 S 125 W, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

1,577.00	Total Permitted
9.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

✓ Federal ✓ Underground State ☐ Surface ☐ County ☐ Loadout Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

☐ Other

Permit Condition #1 states that Hidden Splendor Resources will enter their water monitoring information into the electronic database, EDI. This condition is being met.

Inspec	4000	Ciana	4
insnec	:tors	Signa	THITA

Karl Houskeeper, Environmental Scientist III

Date

Thursday, December 11, 2008

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Thursday, December 11, 2008

Inspection Continuation Sheet

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		$\overline{\mathbf{Z}}$	
2.	Signs and Markers	V		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Thursday, December 11, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

Permit Condition #1 states that Hidden Splendor Resources will enter their water monitoring information into the electronic database, EDI. This condition is being met.

2. Signs and Markers

The mine ID sign was observed at the point of public access to the mine. The sign contained the name of the mine, address, phone number, permit number, and MSHA number. The information is current.

4.a Hydrologic Balance: Diversions

The main diversion along the hillside had a storage bin and several vechicles that were partially blocking the diversion. Kit contacted the surface personnel to make sure that the the itmes were removed. The diversion was still functional with the partial obstructions.